

COUNTY OF MILAM §

PRECINCT NO. 4 §

BK 0091PG0337

ANNUAL ROAD REPORT

1. Condition of each road, culvert, and bridge in the precinct and the primary cause of any road, culvert or bridge degradation: See Attached Forms:
2. Amount of money necessary for maintenance of the precinct roads during the next fiscal year: \$1,700,000.00.
3. Number of traffic control devices in the precinct defaced or torn down: 45
4. Any new road that should be opened in the precinct: 0
5. Any bridges, culverts, or other improvements necessary to place the precinct roads in good condition, and the probable cost of the improvements. On County Road 450 and 455 due to high development, this county road needs to be redone. County Road 421 west end has drainage issues may need a bridge, due to growth in are. County Road 464 Turkey Creek Bridge is still out due to the Harvey Disaster. Lochner Engineering is overseeing this project. This project is a FEMA Project and is not included in this amount. : \$ 1,500,000.00.

Submitted by the undersigned on this 3 day of September.

Commissioner Jeff Muegge, Precinct 4

Signature: Jeff Muegge

Subscribed and sworn to, before me, the undersigned authority, this 3rd day of September 2019.

Notary Public
 Signature: Teresa Wanoreck
 Printed Name: Teresa Wanoreck
 My Commission expires: 02/02/2020



Milam County Precinct 4 - Road Report
September 1, 2018 - August 31, 2019

Road Number	Road Length	Road Surface	# of Bridges	# of Culverts	Road Conditions	Comments
302	3.1	Paved	0	9	Deteriorating - bad spots	Patched; Bladed; trim brush; shredded; worked on drainage;
302A	0.3	Paved	0	1	Dead End	Replaced Culvert;
304	4.9	Gravel	2	13	Developing area - high traffic count,	Replaced culvert and cleared ROW; Pulled culverts; worked on Cottonwood Creek; Worked on it to get it passable; 2/3-2/19/19 installed 1st-bridge; 3/11/19 installed 2nd-bridge on Cottonwood Creek; Assisted Contractor to finish bridge; Cleaned around the approach of the bridge; 4/2/19 opened road; Bladed; Worked on washouts; worked on a culvert; patched and bladed; picked up tree down; Shredded;
304A	1.1	Gravel	0	1	Dead End	Bladed;
305	2.5	Paved	0	4	High traffic count - just north of Rockdale	Cut up fallen tree; Patched; Bladed; Clear ROW; shredded; patched w/blade mix
306	3.2	Paved	0	7		Bladed and hauled base; Shredded; Patched; patched w/ blade mix;
306A	0.1	Gravel	0	0	Dead End	Blade
307	1.1	Paved	0	5		Patched; shredded;
308	0.5	Paved	0	2	Subdivision	Patched;
308A	1	Paved	0	2	Subdivision; dead end	Patched w/blade mix
310	0.5	Paved	0	1	Dead End	Bladed; Patched
311	0.3	Paved	0	2	Subdivision; dead end	Patched;
312	1.7	Gravel	0	4		Bladed;
313	6.5	Gravel & Paved	0	7		Cut up fallen tree; Bladed; patched; shredded;
313A	3.6	Gravel	0	4		Bladed;
313B	1	Gravel	0	1		Bladed; removed fallen trees;
313C	0.3	Gravel	0	2	Dead End	Bladed; replaced road sign;
314	4.2	Gravel	0	10		Bladed;
314B	0.2	Gravel	0	1		Bladed;
317	1.9	Gravel	0	2	Dead End	Bladed and hauled base; Shredded;

BK0091P60338

Milam County Precinct 4 - Road Report
September 1, 2018 - August 31, 2019

412	4.4	Gravel	0	13		Bladed; Hauled base; shredded;
412A	1	Gravel	0	1	Dead End	bladed;
412B	0.1	Gravel	0	0	Dead End	bladed;
417	2	Gravel	0	4		Cut down fallen trees and limbs; Bladed and hauled base; Patched; shredded;
418	1.5	Gravel	0	5		Bladed and hauled base; Cleaned out ditches; shredded;
418B	0.6	Gravel	0	2		Bladed;
418C	0.8	Gravel	0	2	Dead End	Bladed;
419	1.4	Gravel	0	4		Bladed;
420	1.7	Paved	0	8		Picked up fallen tree; Patched;
421	3.7	Gravel & Paved	1	14		Cleaned out ditches; Watered and Packed; Assisted in cleanup after the 4/6/19 tornado; Took a magnet out there to cleaned up nails & screws; Grinded a section of road; Watered road; oiled; Chip-sealed; Bladed and hauled gravel; watered and swept; brushcutting;
421A	0.2	Paved	0	1	(In San Gabriel)	Patched;
426	1.2	Gravel	0	2		Bladed, hauled base; shredded;
427	1.1	Gravel	0	2	(Was 422/425) Dead End	Bladed;
428	1.7	Paved	1	4		Patched; Brush cut;
429	6	Paved-N	1	18		Tree down, cut up; shredded; patched; base on soft spots; Road subject to flood;
430	3.8	Gravel -S				Worked on drainage; Bladed;
430A	0.5	Gravel	0	2	Dead End	Bladed and hauled base; brushcutting;
431	0.85	Gravel	0	4		Bladed and hauled base;
432	4.4	Gravel	0	8		Cleaned up burn pile; Bladed and hauled base; Hauled Weise Gravel;
433	1.1	Gravel	0	2	(Was 428A)	Bladed; water & oiled in front of houses; hauled base;
434	2.32	Gravel	0	3		Bladed and hauled base;
434 LOOP	4.12	Gravel & Paved		14	(Was part of 434)	Bladed; hauled base; oiled in front of some houses;
435	0.4	Gravel		0	(Was part of 439)	Bladed; reset culvert and moved dirt; shredded; Bladed; oiled in front of house;

0091PG0339

Milam County Precinct 4 - Road Report
September 1, 2018 - August 31, 2019

	0.7	Gravel & Paved	0	3	Dead End	
436		Gravel & Paved	0	3	Dead End	Bladed and hauled base; Patching; Shredding; Roadway subject to flooding; P/u dumped tires; Bladed; shredded; Patched;
437	3.3	Paved	1	7	(Was Part of 443)	Bladed; shredded; Patched;
438	2.4	Gravel	0	5		P/u dumped tires; bladed; shredded;
439	1.9	Gravel	0	5		Bladed; hauled base;
440	2.3	Paved	0	8		Patched;
442	2.7	Paved	0	10	(Hwy 79 to 446)	Patched; Bladed and hauled base and blade mix; Bladed; Road subject to flood; Picked up drift wood;
445	1.4	Gravel	3	1	(Thorndale to 440)	Patched; worked on washouts; clean out ditch; Bladed and put out blade mix; Section from 79 approx. .5 mi is deteriorating in spots needs culverts and needs to be redone;
446	8.1	Paved	0	23		P/u dumped tires; Bladed and hauled base; road subject to flooding;
446A	0.4	Gravel	0	2	(McDaniel Road) Dead End	Bladed; shredded; hauled base; worked on ditches;
447	3.3	Gravel	0	7		Shredded; Bladed, watered, oiled and packed in front of house; patched w/blade mix on one end; Bladed;
448	8.5	Gravel & Paved	0	11		Patched washouts; Patched; Bladed; shredded;
448A	0.5	Gravel	0	0	Dead End	Bladed and hauled base; shredded; worked on washouts; Patched; Cut Brush; watered, bladed, and rolled spots in road; High traffic due to high development;
449	4.3	Gravel & Paved	0	5		Bladed and hauled base; Patching; Shredding; Cut brush and trimmed trees;
450	4	Paved	0	8		Bladed and hauled base; shredded; Picked up tires; Hauled raps;
451	0.5	Paved	0	1		Bladed and hauled base; shredded; worked on washouts; Patched; Cut Brush; watered, bladed, and rolled spots in road; High traffic due to high development;
452	0.7	Gravel	0	1	Dead End	Bladed and hauled base; Patching; Shredding; Cut brush and trimmed trees;
453	0.7	Paved	0	4	(Between 450 & 455)	Bladed and hauled base; shredded; Picked up tires; Hauled raps;
454	3.8	Gravel & Paved	0	8		Bladed and hauled base; shredded; Cut brush; cut up tree down; Hauled raps;
455	10.6	Paved		29	High traffic on road. North part has high development;	Patched; Bladed and hauled base; shredded; Hauled blade mix; shredded; Hauled blade mix;

009160340

Milam County Precinct 4 - Road Report
September 1, 2018 - August 31, 2019

456	2.1	Gravel	0	3	Lincoln Lane	Patched washouts; cut brush; shredded; Bladed and hauled Wise Gravel; watered, rolled in front of house;
457	4.3	Paved/Gravel	0	4		Patched; shredded; bladed on back side;
458	2.2	Paved	0	6		Picked up fallen tree; Patched; shredded; Bladed in spots;
458A	3.1	Paved	0	6		Cut back some limbs; oiled, watered, bladed; shredded;
459	1.8	Paved	0	4		Clean-out ditch; worked on washouts; watered & Packed; oiled, watered, bladed; shredded;
460	1.9	Gravel	0	4		Bladed; Clear ROW; shredded;
461	0.4	Paved	0	0		Bladed; hauled base;
462	2.4	Gravel	0	8	(443 Loop)	Bladed; Hauled base; shredded;
463	1.7	Gravel & Paved	0	6	(FM 486 to 437)	Bladed, worked on washouts; hauled base; patched; subject to flooding;
464	2.9	Gravel & Paved	2	4	(FM486 to 434 Loop)	Repaired Brushy Bridge to make passable; Hauled gravel and bladed; brushcutting; FEMA WORK- Bridge 2 on Brushy Creek; working on east side approach; Bridge 1 on Turney Creek is still washed out;
ALL DAY ST	0.5	Paved	0	1	Dead End	Patched;
BEVERLY DR	0.5	Paved	0	0		
BOYD LANE	0.3	Paved	0	2	Dead End	Patched; Bladed and hauled base;
BUSH ROAD	0.9	Paved	0	3	Dead End	Bladed and patched; shredded;
CHAMPION DRIVE	0.55	Paved	0	1	Dead End	Drained ditch; worked on drainage; cut tree limb down;
CUMLEY LANE	1.2	Gravel	0	3	Dead End	Hauled gravel and bladed;
CYPRESS TRAIL	2.2	Paved	0	5	Dead End	Bladed and worked on road; Patched;
ELM CREEK Estates	0.9	Paved	0	2	Dead End	Patched;
GABRIEL'S CROSSING ADD.	0.5	Paved	0	5	Dead End	Patched;
Glendale Dr	0.272	Paved	0	0	Dead End	Patched;
GRIFFIN LANE	0.5	Gravel	0	0	Dead End	Shredded; Bladed hauled gravel;
Inwood Dr	0.131	Paved	0	0	Dead End	Patched;
JOST LANE	0.6	Gravel		2	Dead End	Replaced Road sign and pole; installed cattle guard;
OAK PARK ADDITION	1.45	Paved		5		Bladed; Patched;

00091P0341

Miam County Precinct 4 - Road Report
 September 1, 2018 - August 31, 2019

BK009160342

	1.1	Gravel	0	2	Dead End	Bladed & hauled base; Subject to flooding;
PERRY LANE	1.1	Gravel	0	2	Dead End	Bladed & hauled base; Subject to flooding;
PRAESEL ADDITION	2.45	Paved	0	22		Remove large tree; Patched with bladed mix;
ROCKDALE WEST	0.7	Paved	0	4	Dead End	Patched; Bladed and hauled base; packed and watered;
RUSSEL ADDITION	0.4	Paved	0	0	Dead End	Patched;
SANDOVAL ROAD	0.5	Paved	0	1		
WESTERN HILLS	1.5	Paved	0	5	Dead End	Patched; worked on washouts;
TOTAL MILES	182.943					
TOTAL BRIDGES			11			
TOTAL CULVERTS				445		

Milam County Pct 4 Road Bridges
Gravel, Oil, ETC
September, 2017 to August, 2018

Company	Product	Jan-19	Feb-19	Mar-19	Apr-19	May-19	Jun-19	Jul-19	Aug-19	Sep-18	Oct-18	Nov-18	Dec-18	Total
Boral Material Tech.	Fly Ash (Tons)													0.00
	Macs Ash (Tons)													0.00
Brandon Allen	Gravel													0.00
Cleveland Asphalt Prod.	CRS-2 (lbs)													0.00
	SS-1H (lbs)													0.00
Ergon Asphalt & Emulsions	AE-P (Tons)							3867.00		1922.00				5789.00
	CRS-2 (Tons)	1854.00	591.00	1026.00	1317.00	1606.00	1649.00	13875.00	633.00				1025.00	23576.00
	CSS-1H								1927.00					1927.00
Knife River	5 Sacka Grout (Yds)								70.00					70.00
	High Perf. Cold Mix													0.00
	Hot Mixed-Cold Laid													0.00
Kroeger's Pit	Red Dirt (yds)													0.00
Mine Services	AES-300 Cold Mix (tons)	96.96	64.12	77.08	159.48	0.00	24.72	414.70		368.21	194.66	216.17	39.85	1655.99
	C Rock									268.13				268.13
	DF Blend													0.00
	Torpedo Rock (#16)								11.08					11.08
Svetik Gravel Pit	Gravel													0.00
Texas Crushed Stone	1 1/4 Fill Material													0.00
	1 -2 3/8 Type D													0.00
	1 3/4 -3/4 Ballast #4		98.50		75.28		48.27	439.86						572.61
	1 3/4 Standard Base	1001.65	974.28	958.67	1061.15	853.91	386.85	559.96		413.25	728.05	268.86	637.17	7843.80
	1 3/4 Super Base Test													0.00
	1 x 1/2 Hard Stone	142.96												142.96
	3/4 -3/8 Con Agg							46.14						46.14
	3 x 5" Hard Stone	147.86				142.52								290.38
	Barko Base													0.00
	Broken Boulder 24-0								185.07					185.07

