

BK0091PG0320

ROAD REPORT
MILAM COUNTY
PRECINCT 1
September 1, 2018 –
August 31, 2019

Milam County Precinct 1 Road Report
 September 1, 2018 - August 31, 2019

0K0091PG0321

Road Number	Length	Surface	Bridges	Culverts	Comments
100	0.219	Gravel		yes	Good
101	1.064	Gravel		yes	Needs to be reworked.
102	1.483	Gravel		yes	Good
103	1.734	Gravel		yes	Good
104	7.803	Gravel and sealcoat	yes	yes	Applied 560 yds. of gravel.
104 Loop	0.658	Gravel		yes	Applied 120 yds. of base and 24 yds of gravel.
104 A	0.474	Gravel			Dirt road.
104 B	0.294	Gravel		yes	Applied 42 yds gravel.
104 C	0.442	Gravel		yes	Good
105	1.004	Gravel		yes	Applied 48 yds of gravel.
106	1.011	Gravel	yes	yes	Applied 280 yds of gravel.
107	0.587	Gravel		yes	Good
108	1.161	Gravel		yes	Good
108 A	0.702	Gravel		yes	Applied 304 yds of base and 224 yds of gravel.
109	1.392	Gravel		yes	Good
110	1.329	Gravel		yes	Good
111	0.72	Gravel			Applied 36 yds of base
112	4.158	Gravel		yes	Applied 112 yds of base and 24 yds of gravel and 72 tons of concrete ag
112 A	0.47	Gravel		yes	Good
112 B	0.391	Gravel			Good
113	1.137	Gravel		yes	Good
114	2.158	Gravel		yes	Applied 24 yds of base.
115	2.93	Gravel		yes	Replaced culvert and applied 36 yds of gravel.
115 A	0.172	Gravel			Lake road
116	6.079	Gravel	yes	yes	Good
116 A	0.884	Gravel		yes	Needs gravel in spots.
117	1.354	Gravel		yes	All of road needs gravel
118	1.422	Gravel			Good
118 A	0.632	Gravel		yes	Applied 380 yds of gravel
119	2.796	Gravel	yes	yes	Applied 40 yds gravel.
120	3.528	Gravel	yes	yes	Applied 92 yds of base.
122	0.785	Gravel and sealcoat		yes	Good
123	0.417	Gravel		yes	Good
124	0.547	Gravel			Good
125	0.708	Sealcoat			Good
126	0.475	Gravel			Needs spots graveled.

Milam County Precinct 1 Road Report
 September 1, 2018 - August 31, 2019

BK0091PG0322

Road Number	Length	Surface	Bridges	Culverts	Comments
131	3.205	Sealcoat and gravel			Good
132	2.56	Gravel		yes	Good
143	1.517	Seal coat		yes	Replaced culverts and concreted them in place and ends.
143 A	0.804	Gravel			Good
144	0.964	Seal coat		yes	Good
144 A	0.319	Gravel		yes	Needs gravel in spots.
145	1.993	Sealcoat and gravel		yes	Needs patching.
145 A	1.035	Gravel		yes	Needs gravel in spots.
146	3.3	Gravel		yes	Needs gravel in spots.
147	1.772	Gravel	yes	yes	Applied 40 yds gravel.
150	1.08	Gravel			Applied 24 yds of base.
201	3.199	Gravel		yes	Applied 120 yds of gravel.
202	1.76	Gravel		yes	Applied 640 yds of gravel.
202 A	0.19	Gravel			Needs gravel in spots.
203 Loop	6.575	Gravel and base		yes	Applied 2660 yds of gravel.
204	1.206	Gravel and sealcoat		yes	Applied 248 yds of base.
204 A	0.623	Gravel			Good
204 B	0.468	Gravel			Applied 48 yds of base.
205	1.356	Gravel		yes	Applied 56 yds of base.
205 A	0.32	Gravel			Good
205 B	2.057	Gravel		yes	Good
206	3.296	Gravel		yes	Applied 1,472 yds of gravel and 12 tons cold patch mix
206 A	0.517	Gravel		yes	Good
207	1.449	Gravel		yes	Good
208	3.394	Gravel and sealcoat		yes	Applied 200 tons patch mix.
208 A	0.593	Gravel			Needs gravel in spots.
209	1.649	Gravel		yes	Good
209 A	0.622	Gravel		yes	Good
210	2.62	Gravel		yes	Applied 62 yds of base and 160 yds of gravel.
212	4.154	Gravel		yes	Applied 90 yds of base.
212A	1.36	Gravel		yes	Good
213	1.518	Gravel		yes	Good
214	1.961	Gravel		yes	Applied 1,520 yds of gravel and 110 yds of base.
215	2.882	Gravel		yes	Good
215 A	0.575	Gravel			Applied 92 yds of gravel.
216	1.179	Gravel			Good

Milam County Precinct 1 Road Report
 September 1, 2018 - August 31, 2019

Road Number	Length	Surface	Bridges	Culverts	Comments
216 A	0.738	Gravel		yes	Applied 12 yds of gravel and 20 yds of base.
217	1.495	Gravel		yes	Good
217 A	0.167	Gravel			Good
218	2.602	Gravel	yes	yes	Applied 232 yds of base.
218 A	0.251	Gravel		yes	Good
219	2.014	Gravel			Good
220	1.308	Gravel		yes	Good
221	0.654	Sealcoat and gravel		yes	Applied 96 yds of base and replaced 2 culverts.
222	0.923	Gravel		yes	Replaced culvert and applied 1,380 yds of gravel.
223	1.038	Sealcoat		yes	Good
230	4.051	Gravel	yes	yes	Good
401	1.21	Gravel		yes	Good
402	3.637	Sealcoat and gravel	yes	yes	Good
402 A	0.495	Gravel		yes	Road needs gravel
403	1.732	Gravel	Washed out	yes	Good
404	0.281	Gravel			Good
404 Loop	3.175	Gravel		yes	Needs work.
405	3.136	Gravel	yes	yes	Applied 12 yds of base and 540 yds of gravel.
406	3.975	Gravel		yes	Good
407	3.016	Gravel		yes	Applied 60 yds of base but needs more gravel.
408	2.848	Gravel		yes	Applied 52 yds of base.
409	1.639	Gravel		yes	Applied 240 yds of gravel and 52 yds of base.
410	1.39	Gravel and sealcoat		yes	Applied 140 yds of gravel.
410 A	0.321	Gravel and sealcoat			Good
411	0.993	Gravel		yes	Good
412 West	3.46	Gravel		yes	Applied 44 yds of base 940 tons os rock and 1,200 yds of gravel.
413	1.938	Gravel		yes	Good
414	3.964	Gravel		yes	Applied 40 yds of base.
415	1.345	Gravel		yes	Needs gravel in spots.
416	1.346	Gravel		yes	Applied 940 yds of gravel.
417	2.86	Gravel		yes	Applied 280 yds of gravel and 120 yds of base.
418	3.76	Gravel	yes	yes	Applied 300 yds base 3,020 yds gravel and replaced culverts w/ bridge
418 A	0.794	Gravel	Yes	yes	Good
422	3.087	Gravel		yes	Needs gravel.
422 A	0.252	Gravel		yes	Good
423	1.175	Gravel	yes	yes	Needs some gravel.

PK0091PG0323

Milam County Precinct 1 Road Report
 September 1, 2018 - August 31, 2019

Road Number	Length	Surface	Bridges	Culverts	Notes
424	1.053	Gravel		yes	Needs some gravel.
470	0.659	Gravel		yes	Applied 20 yds of gravel.
Capital Lane	0.942	Gravel		yes	Good
Village Lane	0.185	Gravel			Good
College Lane	0.184	Gravel			Good
Alamo Road	1.164	Sealcoat		yes	Needs to be resealed.
Ben Milam Road	1.011	Sealcoat		yes	Needs to be resealed.
Laughlin Road	0.432	Gravel		yes	Good
Goetz Road	0.666	Sealcoat		yes	Road needs to be sealcoated.
Goetz Road A	0.163	Gravel		yes	Road needs to be sealcoated.
					198.1 Miles of Roads in Precinct 1
					16,120 yards of gravel put on roads.
					2,198 yards of base put on roads.
					224 tons of cold patch mix put on roads.
					964 tons of oversize rock put on roads and around culverts.
					7 Culverts replaced
					1 set of culverts replaced with a concrete bridge.

BK0091PG0324